

Rotary Flames House

Existing Conditions




- A 90m2 rubber play surfacing
- B In ground sensory panels (2)
 Swing with adaptive bucket seat
 Water/Play Table
- C Concrete bollards (3) with lighting

- **D** 1.2 m height black aluminium black fence around perimeter
- **E** sodded areas
- **F** plain grey concrete surfacing

The play area is relatively small for the site of the size of the space. The play value of the components is small. The open picket fence leave the site feeling exposed and any one in the play area on display to the traffic passing by. This is compounded by the fact the playground is adjacent to a bus route. The minor amount of shade within the play area is challenging; the shaded areas are immediately adjacent to the building well away from the play area.












Rotary Flames House

Features



















Alberta Children's Hospital Playground Concepts - Draft