# District 5580 World Community Service (WCS) Matching Grant Application

#### FOR DISTRICT 5580 USE ONLY (once Grant is approved)

17314

District Grant No. WCS -Click here to enter text.	Date Approved: Click here to enter a date.							
District Grant Subcommittee Chair Signature:								
District Rotary Foundation Chair Signature:								
IMPORTANT: A project already started will no	t be eligible for World Community Service funds							
Evaluation: Matching grants support the humanite								

**Explanation:** Matching grants support the humanitarian service projects of Rotary Clubs and Districts. In this section, describe in detail the humanitarian need your project will address, the intent of the project including info on the beneficiaries (how the project will benefit the community in need), how the project will be implemented, and how Rotarians will be directly involved in the project (involvement is required by both the Host Club and International Partnering Club).

Meenakshipuram is a small village 15Kms south of Rajapalayam where our Rotary club is located in South Tamilnadu State of India. The village committee is running a Higher secondary school which is named as Perunthalaivar Kamarajar Higher Secondary School (PK Higher Secondary School) which caters to another 22 surrounding remote villages. 820 students are studying in the school but it has the capacity to accommodate only half of the students. Every year the number of admissions is on the increase and the School Committee find it difficult to accommodate all the children. So Rotary Club of Rajapalayam with the help of their International sponsor District 5580 built a New School Building with 12 Class Rooms in the year 2015. If the school has to be shifted to the new building it has to be shifted on a whole and not in part. So the new school building requires another 6 class rooms in the first floor so that the entire school can be shifted to the spacious new school. So Rotary Club of Rajapalayam in association with District 5580 can complete the project by adding another 6 class rooms in the first floor. The host club Rotarians will form a committee to oversee the project construction and will visit the building during the construction often. The partnering club will be in constant touch with host club and the progress of the construction will be updated with photographs.

Please provide the name of the project site, the city or village, state or province, and country. Provide a detailed map of the area or provide GPS (Global Positioning Site) coordinates.

List multiple locations, if applicable.

Project Site: Perunthalaivar Kamarajar Higher Secondary School Ground.

City/Village: Meenakshipuram Village.

State/Province: TamilNadu.

Country: India.

GPS coordinates (if no map is provided): 9°21 minutes 33.39 seconds N 77°31 minutes 05.82 seconds E

Provide name of ownership of property that structure on which structure is to be built. Meenakshipuram Village School Committee.

Provide a blueprint/detailed drawing of the proposed structure as an attachment. Blue Print Attached.

Provide the estimated length of time needed to complete the project. Six Months.

Describe how the benefiting community will maintain this structure or project (financing of maintenance, etc.) after grant funding has been fully expended and who will be responsible for sustainability of the

structure. : The School Committee is responsible for the sustainability of the Project and the building will be maintained by funds from the Meenakshipuram Village Committee which has a small annual subscription from the people.

Describe specific activities of the Host and International Partners in implementing the project. Apart from funding the project for completion the Host partners will form a Committee for purchase of the Construction materials and oversee the construction activities of the project.

What will the Rotarians who are members of the partner clubs do during the project? Please note that financial support is not considered active involvement. (Refer to *Matching Grant Application Instructions* for suggestions.) The host partners will form a Committee of Rotarians to oversee the project. They will be actively involved in correct purchase of materials and also personally oversee the project at the site frequently till the completion of the project.

Explanation: The Host Partner is the Club or District in the project country. A committee of at least three (3) Rotarians must be established to oversee the project. The primary project contact must be a member of the primary Club identified below. The Project Committee must be composed of members of the sponsoring Rotary Club or NGO for Club-sponsored projects or District for District-sponsored projects. The committee members must be committed for the duration of the grant process. Please provide the primary address for all committee members, as all D5580 information will be sent to this address. It is required that the primary contact (who receives all information from D5580) have an email address to expedite communication.

#### **Primary Rotary Club/District or NGO:**

Club: Name and Number and/or NGO: Rotary Club of Rajapalayam. Charter No: 15941

District: 3212. Country: INDIA

#### **Primary Contact:**

Name: Gopalakrishnan Natarajan. Member ID (if known): 2590008

Club Name: Rotary Club of Rajapalayam. Position: International Service Chairman. Street Address: 41.C, Sevalpatti Street.

City/State or Province/Postal Code: *Rajapalayam. Tamilnadu. India. 626117*. Phone: +91 9842120730 Email Address (Required): drngkrjpm@gmail.com

#### **Project Contact #2:**

Name: John James

Member ID (if known): 5114939

Club Name: Rotary Club of Rajapalayam.

Position: Member.

Street Address: Gopi Electricals, 268, Sankarankovil Road,

City/State or Province/Postal Code: *Rajapalayam. Tamilnadu. India. 626117*Phone: +91 9443132026 Email Address (Required): jvass005@yahoo.co.in

#### Project Contact #3:

Name: T.Jayakumar.

Member ID (if known): 8127379

Club Name: Rotary Club of Rajapalayam. Position: Chairman, District Project.

Street Address: 164, Vallalar Street,

City/State or Province/Postal Code: Rajapalayam. Tamilnadu. India. 626117

Phone: +91 9443396863 Email Address (Required): athielectrix@gmail.com

Explanation: The International Partner is the Club or District outside the project country. In this case, the International Partner would be a Club in District 5580. A committee of at least three (3) Rotarians must be established to oversee the project. The primary contact must be a member of the primary Club identified below. The project committee must be composed of members of the sponsoring Rotary Club(s) for Club-sponsored projects or District-sponsored projects. The committee members must be committed for the duration of the grant process. Please provide the primary address for all committee members, as all D5580 information will be sent to this address. It is required that the primary contact (who receives all information from D5580) have an email address to expedite communication.

#### Primary Club/District:

Club or District Name: FM AM Rotary Club ID Number: 27874

District #: 5580 Country: ⊠USA □CAN

### Primary Contact:

Name: Keith Brokke

Member ID (if known): 1813144 Club Name: FM AM Rotary. Position: International Committee

Street Address: 42754 Engstrom Beach Road

City/State or Province/Postal Code: Dent, Minnesota 56528 USA

Phone: 218-371-9243 Email Address (Required): kbrokke@borderstatespaving.com

#### **Project Contact #2:**

Name: *David Brian Manning*Member ID (if known): 6013490
Club Name: *FM AM Rotary*Position: *International Committee*Street Address: 1915 4th Street S.

City/State or Province/Postal Code: Moorhead, Minnesota 56560

Phone: 218-291-0679 Email Address (Required): davidbrianmanning@gmail.com

#### **Project Contact #3:**

Name: John Johnson

Member ID (if known): 8843299 Club Name: FM AM Rotary Position: International Committee Street Address: 1217 7th Street S.

City/State or Province/Postal Code: Fargo, North Dakota 58103

Phone: 701-412-7185 Email Address (Required): john.johnson@ars.usda.gov

**Explanation**: Official Exchange Rates can be found at: www.rotary.org/newsroom/downloadcenter/support/rates.html. Please use the most recent rate.

NOTE: The host club/district contributions are NOT matched by D5580.

#### ITEMIZED BUDGET TO BE COMPLETED BELOW:

Budget Item # Units Amount Each Subtotal

Attached separately.

Total INR (Attached Separately)

Subtotal all items in country currency: INR 3,000,033.02

Exchange rate used US \$1 = INR 67.00

In US Dollars: \$44,777.00

**Explanation**: Clearly list all financing in US dollars in the section below, noting which funds will be contributed in cash and which will be contributed from D5580 WCS funds. Use of WCS must be approved by the Grants Subcommittee and authorized by the District Rotary Foundation Chair. **The Host Club or** 

**District must provide at least \$100 in cash**, and it is highly recommended that they match as much as possible with "in kind" donations of sweat equity whenever possible.

Note: A project bank account must be established in District 5580 or Host Country before WCS Grant Funds will be distributed. When established and total club/cash contributions have been deposited into the account, the WCS Grant matching funds will be sent directly to the project bank account.

Host Club (Project Country) cash donation: \$ 14,777.00 D5580 Rotary Club(s) or District outside the Project Country:

Cash (US\$): \$15,000.00 Subtotals, Cash: \$29,777.00

**Total Cosponsor Contributions: \$0.00** 

Total Funds requested from D5580 WCS Fund: \$15,000.00

Additional outside funding not matched by WCS fund: \$0.00 Total Project Financing (Must equal budget): \$44,777.00

**Explanation:** Before an application is submitted to D5580, project partners should discuss various planning details. The questions and statements below are a guide to aid project planning. Note that a Rotary Club/District or Rotarian may not own anything purchased with grant funds.

- Identify who will own equipment and maintain, operate and secure items purchased with grant funds.
- Will training in use and maintenance of technical equipment be provided? If so, who will provide such training?
- Is software necessary to operate any items? If so, has software been provided?
- Indicate what arrangements have been made for customs clearance if items will be purchased and shipped from outside the project country.
- Provision of plumbing and electrification to structures where people live or work may be funded with WCS funds. Have plumbing or electrification for equipment and appliances in existing buildings (hospitals, schools, libraries, orphanages, etc.) been considered and funded?

**Explanation**: Authorizations ensure that both partners are aware of, and interested in, pursuing the described project. By signing below, the current Club Presidents for Club-sponsored projects, and current District Grants Subcommittee Chair for District-sponsored projects, as well as the committee members, agree to the criteria listed and affirm their support of the projects.

All Rotary Clubs, Districts and Rotarians involved in this project are responsible to D5580 for the conduct of the project and its subsequent reporting. The signatures of all involved parties confirm that they understand and accept responsibility for the project. Parties may either sign this page or submit a separate letter of commitment.

#### By signing below, we agree to the following:

- All information contained in this Application is, to the best of our knowledge, true and accurate, and we intend to implement the project as presented in this Application.
- The Club/District agrees to undertake this project as an activity of the Club/District.
- We ensure all cash contributions (as detailed in Project Financing) will be forwarded to the proper bank account after approval of the grant.

- or his or her family, or give improper advantage to others to the detriment of D5580. (NOTE: Any and all exceptions must be explained in an attached statement.)
- Interim Reports are due every 6 months until completion of the project. The Final Report
  is due within two months of project completion. Failure to report will result in the club(s)
  returning ALL WCS funds to D5580!

Hnut	Pariner

President (Club-sponsored)

District Grants Subcommittee Chair (District-sponsored)

Name (print): J.Anand.

Title: President.

Rotary Club Name: Rotary Club of Rajapalayam.

NGO: Click here to enter text.

District #: 3212. India.

Signature:

Date: Click here to enter a date.

#### International Partner

Club President (Club-sponsored)

District Grants Subcommittee Chair (District-sponsored)

Name (print): Tom Thompson

Title: President

Rotary Club: FM AM Rotary

District 5580

Signature: 1000

Date: Click here to enter a dyte.

#### Explanation:

A cooperating organization (for example, an NGO) is an organization that is directly involved in the implementation of the project, offering technical expertise and project coordination.

A benefiting entity is the recipient of goods or services and is not considered a cooperation organization. If this project involves a cooperating organization (neither a Rotary Club nor the beneficiary of the project), provide the following:

Name of Organization: Click here to enter text

Street Address: Elick here to enter text

City, State/Province, Postal Code, Country: Click here to enter text.

Office Phone: Click here to enter text

Email Address: Click here to enter text.

A *cooperating organization* (for example, an NGO) is an organization that is directly involved in the implementation of the project, offering technical expertise and project coordination.

A *benefiting entity* is the recipient of goods or services and is not considered a cooperation organization. If this project involves a cooperating organization (neither a Rotary Club nor the beneficiary of the project), provide the following:

Name of Organization: Click here to enter text.

Street Address: Click here to enter text.

City, State/Province, Postal Code, Country: Click here to enter text.

Office Phone: Click here to enter text. Email Address: Click here to enter text. Web Address: Click here to enter text.

Also, have the project contact provide the Project Contact information as listed above.

#### In addition to the above, the following must be attached:

- Letter of participation from *cooperating organization* that specifically states:
  - ✓ Its responsibilities and how it will interact with Rotarians.
  - ✓ The organization's agreement to cooperate in any financial review of the project.

Explanation: Although both partners are responsible for completing the Interim and Final reports, <u>D5580</u> requires that one (1) partner take primary responsibility for submitting the Final Report to <u>D5580</u>. It is recommended that the primary project Club in <u>D5580</u> takes this responsibility.

By signing below, our Club accepts Primary Reporting responsibility.

Print Name: Keith N. Brokke

Rotary Club Name: FM AM Rotary

District 5580

Mentor's Printed Name: Keith N. Brokke

Mentor's Signature: Will No.

Before submitting your WCS Matching Grant Application, please take a moment to review this checklist.

- ✓ Does the project meet all grant policies and guidelines?
- ✓ Does the project description clearly state how the project will assist those in need?
- ✓ Are the activities of the host and international partners clearly explained?
- ✓ How will Rotarians be actively involved in the project?
- ✓ Have both the host and international partners created committees to oversee the project?
- ✓ Are these individuals correctly listed on the Application with their complete contact information?
- ✓ Is a detailed, itemized budget included in the Application?
- ✓ Is ownership of the property on which the structure will be located clearly stated?
- ✓ Is a blueprint/detailed drawing of the structure included?
- ✓ Are all partner contributions listed in the application, noting which are from the WCS fund?
- ✓ Have the Club Presidents from the host and international partners provided their authorizing signatures?


✓ Has the assigned D5580 Mentor signed off with their approval?

## If a cooperating organization is involved, please make sure the following letters are included with the Application:

- ✓ Letter from the organization specifically stating its responsibilities, how it will interact with Rotarians, and agreeing to cooperate in any financial review of the project.
- ✓ Has the D5580 Grants Subcommittee assigned Mentor certified that the Application is complete and eligible?
- \*\*\* Have the partners made copies of all documents for their files prior to submitting them to D5580?
- \*\*\* Completed Applications should be sent to both of the following:
  - ✓ District 5580 Office: *Diane Collins* bigfish@uslink.net
  - ✓ Grants Subcommittee Chair *Blake Crosby* bcrosby@far.midco.net

If you have any questions or concerns, please contact the <sup>1</sup>Grants Subcommittee Chair.

<sup>&</sup>lt;sup>1</sup> RI District 5580 Revision: January 02, 2016



Itemized Budget

170		budge		
NO	BUDGET ITEMS	UNITS	AMOUNT	SUB
			INR	TOTAL
1	Reinforced cement concrete 1:2:4 using 20mm HBGS jelly all RCC items	136.02 Cu.M	11,500.00	1,564,259.81
2.	Providing and laying brickwok with first class bricks in super-structure	149.32 Cu.M	3,000.00	44,761.77
3.	Plastering with CM 1:5, 15mm thick over the super structure Outside Plastering	1118.50 Sq.M	280.00	3,13,180.65
	Inside Plastering	721.61 Sq.M	280.00	202,051.23
4.	Ceiling plastering with CM 1:4, 10mm thick, soffit of all the RCC	572.47 Sq.M	280.00	160,291.15
5.	Outside by Ramcem two coats Outside Plastering	1,118.50 Sq.m	15.00	16,777.53
6.	Inside Colour washing by ramcem two coats Inside plastering	721.61 Sq.m	15.00	10,824.17
7.	Ceiling by Ramcem with White washing two coats and all labours etc., complete. Ceiling plastering	572.47 Sq.m	15.00	8,587.03
8.	floor finished by 1:1/2:3 mix with power trowel Ellise pattern type	536.80 Sq.m	200.00	107,359.62
9	Supplying and fixing in place shutter for doors made out of madras chipboard and angle iron frame of 40*40*6	23.79.Sq.m	1,800.00	42,825.28
10.	Providing and Fixing of steel window including painting	31.41 Sq.m	120.00	37,695.17
11.	Weathering course using 20mm size broken brick jelly and lime over RCC roof slab, Portico, top including the cost of laying 80mm depth.	46.43 Cu.m	1,900.00	88,219.61
	TOTAL			3,000,033.02
	USD. (1USD= INR 68.00)		· .	40,057.00

#### **ABSARA CONSULTANCY**

( Planners, Builders, Valuers & Architect )

Er. B. Muthukumarasamy, B.E. (Civil)., M.E.(Struct).,

AMIE., FIV., MISTE.,

Chartered Engineer - 086521 / 7 Approved Valuer, F - 13807 No: 35, Ayothiram Nagar, Madasamy Koil Street, Rajapalayam - 626 117. Mobile: 94433-31465

Date: - 07-06-2016

Name of Work: Detailed cum Abstract Estimate for the Proposed Additional Construction of RCC Roof Terraced building in First floor for Perunthalaivar Kamarajar Rotary International higher secondary school at S.No.518/20,529/54,2C1,2C2&2C3, Meenachipuram panchayat, Puttur village, Rajapalayam Union and Taluk, Virudhunagar District.

Applicant name :- The Correspondent & Secretary

S.NO	DESCRIPTION OF WORK	NO.	L	В	D/H	QTY	UNIT	RATE	AMOUNT
	FIRST FLOOR :-					_			
1	Reinforced cement concrete 1:2:4								
	using 20mm HBGS jelly all RCC								,
	items								
1	R.C.C. Column:								
	Column - (0'-9"x1'-6")	32	0.75	1.50	12.00	432.00			
	Column - (1'-6"x0'-9")	4	1.50	0. <i>7</i> 5	2.75	12,38			
	Column - (0'-9"x0'-9")	10	0. <i>7</i> 5	0. <i>7</i> 5	2.75	15.47			
	R.C.C. Lintel Beam :								
	Building -West side beam	1	188.17	0.75	1.00	141.13			
	Building - Eest side beam	1	171.00	0. <i>7</i> 5	1.00	128.25			
	Building - North and south beam	2	22.25	0.75	1.00	33.38			
	Corridor - East side beam	1	200.17	0.75	1.00	150.13			
	Corridor - North and south beam	2	10.00	0.75	1.00	15.00			
	Roof Beam:			ĺ	İ				
	Roof beam - (Ver)	14	23.75	0.75	1.50	374.06			
	Roof beam - (Hor)	1	18.67	0.75	1.50	21.00			
	Roof beam - (Ver)	2	11.50	0.75	1.50	25.88			
	Roof Slab :				ļ		İ		
	Building	1	200.17	34.50	0.50	3452.93			
		Ш				4801.60			
						136.02	Cu.m	11500.00	1564259.81
	Providing and laying brickwok with								
	first class bricks in super-structure								
	Cross wall (Ver)	8	22.25	0. <i>7</i> 5	10.50	1401.75			
	Cross wall (Hor)	1	188.17	0.75	12.00	1693.53		İ	
	Cross wall (Hor)	1	171.00	0.75	12.00	1539.00			
	Corridor - East side wall	1	186.67	0.75	2.75	385.01		į	
	Corridor - North and south wall	2	9.25	0.75	2.75	38.16	i		
	Parapet wall	1	466.34	0.75	2. <i>7</i> 5	961.83		į	ŕ
	Deductions:-		l	l		İ		į	
	Window - (SW)	20	4.00	0.75	4.00	-240.00		•	
	Window - (SW1)	1	4.00	0. <i>7</i> 5	4.50	-13.50	1		
	Door - (D)	8	4.00	0.75	8.00	-192.00			
	Lintel beam					-302.75			
]			<u> </u>			5271.02			
						149.32	Cu.m	3000.00	447961.77
	Plastering with CM 1:5, 15mm thick								
İ	over the super structure	Ī		i	-		ļ	į	

S.NO	DESCRIPTION OF WORK	NO.	L	В	D/H	QTY	UNIT	RATE	AMOUNT
	Outside Plastering								
	Building - walls alround	1	430.67	-	12.50	5383.38			
	Parapet wall - outside	1	469.34	-	2.75	1290.69	į		
	Parapet wall - Inside	1	463.34	-	2.75	1274.19			
	Parapet wall - Top	1	466.34		l -	349.76			
	Pillar	32	1.50	:	12.50	<u> </u>	;		
	Corridor - Outside	1	221.62	•	6.75		:		
	Corridor - Inside	1	218.67		6.75		:		
	Corridor lintel beam bottom	i			0.73	147 6.02 16 <b>5</b> .13	:		
	Corridor lintel beam bottom	1	220.17	0.75	-				
		1				12035.09 1118.50		280.00	212100.65
	Incide Plactering		-			1110.50	5q.m	200.00	313180.65
	Inside Plastering Classroom 1	,	07.00		12.00	1164.00			
		1	97.00		12.00				
	Classroom 2	1	96.84	-	12.00		: :		
	Physics lab	1	120.16	-	12.00				
	Staircase portion	1	į	-	12.00		i i		
	Chemistry lab	1	114.16	-	12.00	1369,92			
	Classroom 3	1	96.34	-	12.00	1156.08			
	Classroom 4	1	96.50	-	12.00	1158.00			
	Deductions:-		İ						
	Steel window - (SW)	20	4.00	0. <i>7</i> 5	4.00	-240.00			
	Steel window - (SW1)	1	4.00	0.75	4.50	-13.50			
	Door - (D)	8	4.00	0.75	8.00	-192.00			
						7764.54	Sq.ft		
						721.61	Sq.m	280.00	202051.23
4	Ceiling plastering with CM 1:4,							1	
	10mm thick, soffit of all the RCC			i					
	surface							İ	
	Class room 1	1 1	26.25	22.25	-	584.06		İ	
	Class room 2	1 1	26.17	22.25		582.28			
	Physics lab	1	37.83	22.25		841.72	l	İ	ì
	Staircase portion	1	17.25	22.25	-	383.81	İ		
	Chemistry lab	1	34.83	22.25	-	774.97	İ	Ī	
	Class room 3	1	25.92	22.25	-	576.72			1
	Class room 4	1	26.00	22.25	-	578.50			
	Corridor	1	198.67	9.25	+	1837.70 <b>6159.76</b>	C~ ft	<u> </u>	
		╀┼				572.47		280.00	160201.15
5	Outside by Ramcem two coats	┢─╂			-	0/2/1/	թվ.ա	200.00	160291.15
J	Outside By Kanicem two coats  Outside Plastering				ļ	1110 50	c	15.00	1/444 50
	Outside Plastering					1118.50	oq.m	15.00	16777.53
4	Incide Colour weeking by some		į	İ	İ	Ì	•	į	
	Inside Colour washing by ramcem		ŀ	-					ļ
	two coats	•				701 61		45.00	40.004.71
_	Inside plastering		ļ	1	ļ	721.61	oq.m	15.00	10,824.17
7	Ceiling by Ramcem with White		Ī	İ		1		l	
	washing two coats and all labours		į	İ		!		İ	ĺ
	etc., complete.		į	-	ļ	ENO 411	_	<b>4 .</b> 00	0000000
	Ceiling plastering					572.47	5q.m	15.00	8587.03
			[		-		ļ		

S.NO	DESCRIPTION OF WORK	NO.	L	В	D/H	QTY	UNIT	RATE	AMOUNT
8	floor finished by 1:1/2:3 mix with								
ļ	power trowel Ellise pattern type								
	flooring			ĺ		l			
	Class room 1	1	26.25		ī	584.06	•		
	Class room 2	1	26.17	22.25	-	582,28			
]	Physics lab	1	37.83	:	•	841.72	.]		
	Chemistry lab	1	34.83	22.25	-	774.97			
	Class room 3	1	25.92	22.25	-	576.72			
	Class room 4	1	26.00	•	•	578.50			
	Corridor	1	198.67	9.25	-	1837.70			
						5775.95			
						536.80	Sq.m	200.00	107359.62
9	Supplying and fixing in place shutter								
ļ	for doors made out of madras	l i							
	chipboard and angle iron frame of								
	40*40*6 frames for door of mild steel								
	angle sections joints including								
ļ	painting								
	Door - (D)	8	4.00	-	8.00	256.00	Sq.ft		
						23.79	Sq.m	1800.00	42825.28
10	Providing and Fixing of steel								
	window including painting								
	Steel window - SW	20	4.00	-	4.00	320,00			
	Steel window - SW1	1	4.00	-	4.50	18.00			
						338.00			
						31.41	Sq.m	1200.00	37695.17
11	Weathering course using 20mm size			i					
į	broken brick jelly and lime over RCC			İ	!				
	roof slab, Portico, top including the	l		İ	Ì			į	
	cost of laying 80mm depth and well	ļ		ļ	ļ			Ī	
	beaten with wooden beaters etc., for			ļ	ŀ				
	the required slope so as to drain the	ļ		ļ	ļ			į	<u> </u>
	Building	1	198.67	33.00	0.25	1639.03	Cft	<b>.</b>	
						46.43	Cu.m	1900.00	88219.61
		FIRST FLOOR TOTAL AMOUNT =							3000033.02

Say Rs.30,00,000/-Rupees Thirty lakhs only



### RUIARI CLUB UF KAJAPALAYAM

R.I.District 3212 \* CHARTER No. 15941\* Chartered On 19-12-1966 Charter President Rtn. MPHF. P.R. RAMASUBRAHMANEYA RAJHA, B.Sc.,



President Rtn. PHF. J. Anand Secretary Rtn.V. Ramsankar Raja

Treasurer Rtn. PP.PHF, J. Santhosh

Date: 26.09.2016

To, The President, FMAM Club, District 5580, USA.

Dear President,

Rotary Club of Rajapalayam has received a request letter from the Meenakshipuram Village School Committee regarding addition of Six Class Rooms in the First Floor of the Existing School Building already built by Bricks and Mortar project of your district in the year 2014-2015. Since the State Government does not permit the existing old school to be shifted in part, the school committee has given the request for addition of Six more class rooms in the first floor. The building plan and the estimates are attached with the application for another Bricks and Mortar project. Kindly consider favorably and sanction the project.

Thank you.

Yours in Rotary,

Rtn. J. Anand. President.

# Perunthalaivar Kamarajar Higher Secondary School

MEENAKSHIPURAM - 626 111.

From

Rajapalayam (Tk), Virudhunagar (Dt)

©04563 - 250180

R. Rajendran, Secretary Headmaster.

PERUNTHALAIVAR KAMARAJAR HIGHER SECONDARY SCHOOL **MEENAKSHIPURAM - 626 111.** 

Rajapalayam (Tk), Virudhunagar (Dt)



To

Dr. N. Giopalakrishnan AVL,

Respected Sir,

Subject:

Date: 20.07.2016

#### Reference:

Greetings and thanks to Rajapalayam Rotary Club. In the academic year 2015-2016. We received 60,000 US dollars from Bricks and Mortar Project of District 5580, USA through your efforts and through Rajapalayam Rotary Trust. We have built a new school with 14 class rooms in ground floor through the contribution and we, the Management of P.K.HSS, Teachers, Students and People of Villages in and around Meenakshipuram thank you all for the same.

On behalf of our Management Committee, We put a humble request before you. We want to shift our school from the old building to the new building and for that we need 6 more Class rooms in the First Floor. We request you to build 6 more Class room So that we could shift our school from the old building to the new building.

(We have already given this request to the visiting USA team from District 5580 in February, 2016.)

We grow with Rotary Club of Rajapalayam and our Villages are also growing with the Rotary Club of Rajapalayam.

Thanking You.

r. K. Hr. Sec. School deenakshipuram-626 111 Rajapalayam-(T.K)

Your's Faith fully,

Secretary

P. K. Hr. Sec. School Meenakshipuram-626 111. Rajapalayam (T.K.).