




Zack Bennett.

The size difference between NZ and Antarctica





Early Explorers whose huts have been restored.





Arrival time.

Red = American transportation, Green = NZ transportation



Shackleton's
British Antarctic Expedition, Cape Royds, 1907 - 1909



Panasonic

Before and after restoration of Shackleton's Hut

Shackleton's Hut
British Antarctic Expedition, Cape Royds




Panasonic



Panasonic



Panasonic



British Antarctic Expedition, Cape Evans, 1910 - 1913



Panasonic

Before and after restoration of Scott's Hut, Cape Evans

Scott's
British Antarctic Expedition, Cape Evans



Panasonic

Captain Robert Falcon Scott's 1911 expedition base, Cape Evans

Conservation status:

- 5 year carpentry programme completed
- 7 year artefact conservation programme completed
- 11,500+ artefacts conserved
- Ongoing monitoring and maintenance programme in place





Blubber sump - Cape Evans






A typical field hut where Zack slept





Before and after of Scott's Hut, Hut Point



Saving Scott's Discovery Hut, Hut Point

Conservation status:

- 2 year carpentry work programme completed
- 500+ artefacts conserved, work programme completed
- Ongoing monitoring and maintenance programme in place




Borchgrevink's Hut, Cape Adare. The before shot

Borchgrevink's British Southern Cross Expedition, Cape Adare, 1898 - 1900



The after shot



Find out more information about the Antarctic Heritage Trust:

